

**Shriners Hospital for  
Children**

Chicago, Illinois



The Hill Group, acting as Prime Contractor, replaced a 17,500 CFM air handling unit serving Operating Rooms and Intensive Care units.

The existing ductwork had excessive integrity issues. The ceilings were removed to carefully repair and seal the supply, return and exhaust ductwork. This ductwork was also thoroughly cleaned. Hill Mechanical Services Test and Balance technicians were able to accurately balance the system.

This was the first time the hospital had ever shut down the OR's or ICU's. Shriners was very apprehensive that this amount of work could be completed within a two month schedule. The Hill team finished one week early.